



Structured Stretch Cotton Cap

HOW TO MEASURE

HATS

Measure the circumference around the head,
above the eyebrow and at the widest part of the head.
Divide number by 3.14 for hat size.

SIZE CHART

	S/M	M/L	L/XL
Hat Size	6 7/8 - 7 1/4	7 1/8 - 7 1/2	7 3/8 - 7 3/4